



AFFECTED VEHICLES
MODEL: 2003 GALANT
2003-2004 ECLIPSE
2003-2004 ECLIPSE SPYDER

December, 2003

RE: IMPORTANT SAFETY RECALL NOTIFICATION: SR-03-003

Dear Mitsubishi Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Mitsubishi Motors North America, Inc. has decided that a defect that relates to vehicle safety exists in certain 2003 and 2004 Galant, Eclipse, and Eclipse Spyder models.

- What is the safety issue?** The fuel return line hose fitting on the fuel pump may be restricted, causing excessive fuel pressure to build up in the fuel injection system. Excessive fuel pressure may result in the fuel return hose becoming dislodged from the fitting, resulting in fuel leakage. Fuel leakage in the presence of an ignition source could result in a fire.
- What you should do:** Please call your Mitsubishi retailer immediately to schedule a repair date. When you bring your vehicle in, show the retailer this letter. (If you misplace this letter, the retailer will still make the repair, free of charge.)
- What your retailer will do:** The retailer will check the fuel return system in your vehicle. If necessary, the retailer will replace the fuel pump.
- How long will it take?** The time needed for the actual repair is about 30 minutes. While your retailer may need your vehicle for a longer period of time due to service scheduling issues, every effort will be made to minimize your inconvenience or delay.
- Have you changed address or sold your vehicle?** If you have changed your address or sold the vehicle, please fill out the enclosed postcard and mail it to us.

If you have any trouble getting your vehicle repaired promptly and at no charge, or if you have already paid to have this condition repaired, you can seek a refund by contacting Mitsubishi Customer Connections at (888) MITSU-2003 (888-648-7828). Hours: Monday - Saturday 7 a.m. to 10 p.m. (Central Standard Time).

If after contacting Mitsubishi Customer Connections, you still have a problem having your vehicle repaired promptly and without charge, write to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street SW, Washington, D.C. 20590, or call the Auto Safety Hotline toll-free (888) 327-4236.

Mitsubishi is committed to making your safety our first concern, and we sincerely regret the inconvenience to you caused by this recall.

[Notice to Lessors: If you are a lessor as of the date of this letter, you have an obligation under federal regulations (49 CFR Part 577) to provide the lessee of the above referenced vehicle with a copy of this letter by first class mail within ten days of receipt. Also, you must maintain a record which identifies the lessee to whom you sent a copy of this letter, the date you sent it, and the vehicle identification number (VIN) of the subject vehicle.]

Sincerely,

Richard Donnelson
Director, Service and Product Support

SR-03-003
C0304AXX